MEASURE & CONTROL

SPEEDGOB 3



Measures length & velocity of Gobs, and gives a notion of temperature of gob between shear point and blank load.

An invaluable aid to the machine operator to optimise production and assist in problem solving.

- single device sensor optics compatible with small and large gobs
- temperature sensor gives an indication of temperature in C° or F°
- measure units changeable by joystick: meter/s
  inch/s
- screen on the handle for direct reading
- more compact reading head
- rechargeable battery
- universal charger (USA, UK, rest of Europe)
- memorised data can be exported to PC in Excel via USB cable
- supplied in suitcase with padded interior

Rondot

RISE Group

Rondot S.A.S.

9 rue Jean Elysée Dupuy
69410 - Champagne au Mont d'Or - FRANCE

Tel: + 33 (0)4 72 52 08 60
Email: sales@rondot-sa.com

Local Distributor